



The reproduction, distribution and utilization of this document as well as the communication of its contents to others without explicit authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. © Pfisterer



Werkstoff elektrisch leitend, unmagnetisch, geerdet
Material electrically conductive, non-magnetically, grounded



Typisches Anziehdrehmoment für
Schraubenverbindung A2/A4-F70
*Typical tightening torque for
Screw connection A2/A4-F70*

- 1 Fläche blank für elektrischen Kontakt
Alle Kontaktflächen mit Kontaktschutzfett
P1 (002 996 001) bestreichen
*This contact area has to be clean,
grease insulator surfaces with
contact grease P1 (002 996 001)*
- 2 Befestigung des Isolators mit 4 Sechskantschrauben
M12x25 incl. Scheiben (nicht im Lieferumfang)
*Fastening of the insulator with 4 hexagon bolts
M12x25 incl. washers
(not included in the scope of delivery)*
- 3 Zur Befestigung der CONNEX Kabelanschlussteils
For mounting the CONNEX cable connection part
- 4 Erdungsschraube 2xM12x40, auch nutzbar für Montage
Vorrichtung während des Steckvorganges
*Earthing screw 2xM12x40, also usable for mounting device
during the plugging process*