

## In-Service Test for Two-Pole Earthing and Short-Circuiting Devices

PFISTERER have been successfully carrying out in-service tests in their own testing facility for many years. The earthing and short-circuiting devices are tested according to the specifications, and immediately adjusted or repaired if necessary. Whenever extensive repairs are necessary, we give a cost quotation.

When the tests are completed, the results are documented in detail.

To request an In-service test, please contact your local sales representative.

Customers in Germany are requested to use the following mailing address:

PFISTERER Kontaktsysteme GmbH  
Bereich Instandhaltungsprüfung  
Bahnhofstraße 30  
89547 Gerstetten - Gussenstadt  
Germany

Phone: +49 7323 83 634 or +49 7323 83 815

E-mail: [service-whp@pfisterer.com](mailto:service-whp@pfisterer.com)



*Picture may vary.*

### Technical Data

---

**Article no.**

**200 000 042**

---