

In-Service Test for Test Case DSA and Interfaces

PFISTERER have been successfully carrying out in-service tests in their own testing facility for many years. The voltage detecting systems are tested according to the specifications, and immediately adjusted or repaired if necessary. Whenever extensive repairs are necessary, we give a cost quotation.

When the tests are completed, the results are documented in detail.

To request an In-service test, please contact your local sales representative.

Customers in Germany are requested to use the following mailing address:

PFISTERER Kontaktsysteme GmbH
Bereich Instandhaltungsprüfung
Bahnhofstraße 30
89547 Gerstetten - Gussenstadt
Germany

Phone: +49 7323 83 634 or +49 7323 83 815

E-mail: service-whp@pfisterer.com



Picture may vary.

Technical Data

Article no.

200 000 200 00335
