

## In-Service Test for EURO-Test HR / LRM

PFISTERER have been successfully carrying out in-service tests in their own testing facility for many years. The voltage detecting systems are tested according to the specifications, and immediately adjusted or repaired if necessary. Whenever extensive repairs are necessary, we give a cost quotation.

When the tests are completed, the results are documented in detail.

To request an In-service test, please contact your local sales representative.

Customers in Germany are requested to use the following mailing address:

PFISTERER Kontaktsysteme GmbH  
Bereich Instandhaltungsprüfung  
Bahnhofstraße 30  
89547 Gerstetten - Gussenstadt  
Germany

Phone: +49 7323 83 634 or +49 7323 83 815

E-mail: [service-whp@pfisterer.com](mailto:service-whp@pfisterer.com)



*Picture may vary.*

### Technical Data

---

**Article no.**

**200 000 200 00336**

---